

ΩMEGA

Health Care



K-3



Function.	description
Accuracy	±0.2 degrees
Response time	0.5s
Abnormal automatic alarm	flashing+"DI DI"sound
Charging method	USB charging or battery
Auomatic measurement	measuring distance 5cm~10cm
input	USB DC4.2-5V
Standby	About one week
Weight	350g
Install method	nail hook, double-sided adhesive sticking, bracket fixing
Dimensions	170*115*140mm
operating temperature	10°C~40°C (Recommend 15°C-35°C)
Infrared measuring range	0~50°C
Standby	5s (Red dot dynamic cycle)
Screen	Digital display

Address : 3 Shenton Way #16-08 Shenton House Singapore 068805

Email: international@omega-h-c.com

WWW.omega-h-c.com